



WILDLIFE PROOFING: BEFORE AND AFTER PHOTO GALLERY



See the Difference Professional Exclusion Makes. A picture is worth a thousand words—especially when it comes to wildlife control. This gallery shows real examples of Minnesota homes before and after professional wildlife proofing, highlighting the importance of proper removal, exclusion, and home protection.

Why Before & After Matters

Before and after photos show how pest entry points are identified, sealed, and animal-proofed with durable materials that block pests and wildlife while withstanding harsh weather. This proves the work was done right and delivers long-term protection for Minnesota homes.

Attic and crawl space infestations



BEFORE



AFTER

The Damage

- Squirrel infestation
- Contaminated crawl space
- Nested insulation
- Forced entry points

The Repairs

- Cleaning and disinfection
- Safe removal of wildlife
- Repaired attic structure
- Replaced insulation

Sealed entry points



BEFORE



AFTER

The Damage

- Forced entry & roofline damage
- Insulation damage from wildlife
- Water intrusion point

The Repairs

- Cleaning and disinfection
- Safe removal of wildlife
- Repaired roof structure

What Expert Animal-Proofing Should Look Like



Correct animal-proofing seals all entry points with durable, chew-resistant materials to prevent re-entry and withstand Minnesota's harsh weather. Our custom metal repairs are secure, weather-tight, and blend seamlessly with your home. See photos above for authentic examples.